

A119 RUN ON WEAR PLATES

PART #	BATCH #	DESCRIPTION OF FINDINGS
D3849-3 REV PC1	B89419	TEST FITTED ON SKID TUBE. FIT TIGHT TIGHT ON SKIDTUBE BORE SEE PICTURES
D3901-3 REV PD1	B89420	QTY X 4 BARS SCRAP DUE TO WELD BREAKING.(TOO MUCH HARDFACING) MACHINED LONG TO BE ABLE TO MACHINE. ACCETABLE SEE PICTURES
D3849-043 REV PC4	B89487	FITS VERY WELL. TIGHT ON SKIDTUBE ROUND HOLES LINE UP. NO NEED FOR CLAMPING LIKE OTHER WEAR PLATES NO LARGE GAP ON THE AFT END OF THE PLATE TO TUBE SEE PICTURES
D3849-1 REV PC2	B89453	TEST FITTED ON SKID TUBE. FIT TIGHT WEAR BAR SLOTS MOVED TIGHT ON SKIDTUBE BORE SEE PICTURES
D3901-1 REV PD3	B89452	QTY X 4 BARS SCRAP DUE TO WELD BREAKING.(TOO MUCH HARDFACING) MACHINED LONG TO BE ABLE TO MACHINE. ACCETABLE SEE PICTURES
D3849-041 REV PC1	B89486	FITS VERY WELL. TIGHT ON SKIDTUBE ROUND HOLES LINE UP. NO NEED FOR CLAMPING LIKE OTHER WEAR PLATES NO LARGE GAP ON THE FWD END OF THE PLATE TO TUBE SEE PICTURES